

Temperature & Humidity Sensor

Temperature Sensor



The Temperature Sensor is tamper proof to stop inadvertent alteration of the temperature set point. The unit is electro mechanical with a range between 10 - 30°C.

Temperature & Humidity Sensor



The Temperature and Humidity Sensor is tamper proof to stop inadvertent alteration of the temperature or humidity set points. Both sensors are electro mechanical devices with a range between 10 - 30°C for temperature and 30 - 100% for humidity.



**3 Kent Road, Dagenham, Essex, RM10 8HA,
United Kingdom**

Tel: +44 (0) 845 686 6066

Fax: +44 (0) 845 686 6067

Email: info@resikom.com

Web: www.resikom.com